

Product Discontinuation Notice PDN2002-02

Discontinuation of the XC4000XLT family

Overview: Xilinx will discontinue all device/speed/package combinations of the XC4000XLT product family (see table below).

Products Affected:

<u>Discontinued Device</u>	<u>Recommended Replacement</u>
XC4013XLT-1PQ208C	XC4013XLA-09PQ208C
XC4013XLT-09PQ208C	XC4013XLA-09PQ208C
XC4013XLT-1PQ240C	XC4013XLT-09PQ240C
XC4013XLT-09PQ240C	XC4013XLT-09PQ240C
XC4028XLT-1HQ240C	XC4028XLA-09HQ240C
XC4028XLT-09HQ240C	XC4028XLA-09HQ240C
XC4062XLT-1HQ240C	XC4062XLA-09HQ240C
XC4062XLT-09HQ240C	XC4062XLA-09HQ240C
XC4062XLT-1BG432C	XC4062XLA-09BG432C
XC4062XLT-09BG432C	XC4062XLA-09BG432C

Reason for Change: The XC4000XLT family has declined in customer usage to the point where continued manufacturing is becoming no longer economical.

Key Dates:

Final orders accepted until 15 January 2003

Final deliveries on or before 15 April 2003

Replacement Devices: Assistance in planning for replacement of the above device combinations is available. Please contact your [Xilinx Sales Representative](#) for more information.

Response: Immediate response to this notification is not required. Please contact your [Xilinx Sales Representative](#) for help with replacement devices. For additional information or questions, please contact the Xilinx Quality Assurance group at pcn@xilinx.com, or directly by fax at (408) 369-1718.